

Brasscraft Manufacturing Company

BrassCraft. PLUMBSHOP®



COBRA®



Friedman & Dorrans Sales, Inc.

CURRENT INVENTORY AS OF SEPTEMBER 21, 2024

STOPS & GAS FLEX:



G2CR19X C (5/8" O.D. X 3/8" O.D. ¼-turn CP angle stop) – 1045

G2CR14X C (5/8" O.D. X 3/8" O.D. ¼-turn CP straight stop) – 150

G2CR09X C (5/8" O.D. X 1/4" O.D. ¼-turn CP angle stop) – 209

G2PS19X C (5/8" push. X 3/8" O.D. ¼-turn CP angle stop) - 15

PLB100X P (5/8" O.D. X 3/8" O.D. ¼-turn CP angle stop) – 1260

PLB111X P (5/8" O.D. X 1/4" O.D. ¼-turn CP angle stop) – 180

PLB200X P (5/8" O.D. X 3/8" O.D. ¼-turn CP straight stop) – 120

SCR19X C (5/8" O.D. X 3/8" O.D. ¼-turn CP LK angle stop) – 140

G2R15X C (3/8" FIP X 3/8" O.D. ¼-turn CP angle stop) – 100

G2R17X C (1/2" FIP X 3/8" O.D. ¼-turn CP angle stop) – 175

Brasscraft Manufacturing Company

BrassCraft. PLUMBSHOP®



COBRA®



Friedman & Dorrans Sales, Inc.

CURRENT INVENTORY AS OF SEPTEMBER 21, 2024

SUPPLY LINES & ADAPTERS:



1-12A C (3/8" X 12" CP LAV TUBE) – 300

1-20A C (3/8" X 20" CP LAV TUBE) – 300

1-12DE C (3/8" X 12" CP CLOSET TUBE) – 300

1-20DE C (3/8" X 20" CP CLOSET TUBE) – 150

PLS1-12A F (3/8" X 1/2" FIP X 12" SS LAV TUBE) – 75

PLS1-16A F (3/8" X 1/2" FIP X 16" SS LAV TUBE) – 0

PLS1-20A F (3/8" X 1/2" FIP X 20" SS LAV TUBE) – 250

PLS1-9DL F (3/8" X 7/8" X 9" SS CLOSET TUBE) – 50

PLS1-12DL F (3/8" X 7/8" FIP X 12" SS CLOSET TUBE) – 25

PLS1-16DL F (3/8" X 7/8" FIP X 16" SS CLOSET TUBE) – 100

PLS1-20DL F (3/8" X 7/8" FIP X 20" SS CLOSET TUBE) – 100

PLSL12-72WA P (3/4" FHT X 3/4" FHT X 72" SS WASH MACHINE) - 10

Brasscraft Manufacturing Company

BrassCraft. PLUMBSHOP®



COBRA®



Friedman & Dorrans Sales, Inc.

CURRENT INVENTORY AS OF SEPTEMBER 21, 2024



PLS1-12KC F (3/8" X 3/8" X 12" SS DELTA TUBE) – 75

PLS1-20KC F (3/8" X 3/8" X 20" SS DELTA TUBE) – 100

PLS1-12DW F (3/8" X 3/8" X 12" SS DW TUBE) - 100

PLS1-20DW F (3/8" X 3/8" X 20" SS DW TUBE) - 100

63-6-8WX CD (3/8" FEM COMP X 1/2" O.D. COMP CP ADAPTER) – 70



TWV3SRX – SWEAT X IPS TANKLESS SERVICE VALVE KIT W/PRV – 6